

U. S. Department of Agriculture  
FOREST SERVICE

*Posted L-9*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *14N* R. *29W* *5th* Mer.

*1/4* Corner common to Sections  
*16*, and *17*

Corner consists of a *Ash Post* (~~not~~) in place  
State condition *Weathered*

Dimensions above ground *3.5" dia. 2' 6" ht.* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION			
N	W	S	E
	<i>1/4</i>		<i>1/4</i>
	<i>5</i>		<i>5</i>
	<i>17</i>		<i>16</i>

DIAGONAL POSITION			
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

*W. J. ...*  
(Signature) \_\_\_\_\_  
**ENGINEER**  
(Title) \_\_\_\_\_  
*3/25/95*  
(Date) \_\_\_\_\_

*L-9*

Corner again.


Give any further facts which will aid in finding this

~~corner~~ distant.

10.  
From which this Corner bears side of **OW**

tree **3.5** inches diameter, on the **N**

**OW** Metal Location Poster is on a



(Please sketch of topography near Corner)

Mer. 1-9

T 191N R. 29W

5th