

U. S. Department of Agriculture

FOREST SERVICE

*Chippewa* *Trusted* *J-9*  
NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141* R. *29* Mer. *5*

*Sec* Corner common to Sections  
*8, 9, 16, and 17*

Corner consists of a \_\_\_\_\_ (not) ~~in place~~



State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_ *Dak*

Diameter \_\_\_\_\_ *12"*

Bearing \_\_\_\_\_ *N45°E*

Distance \_\_\_\_\_ *108'*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*P. H. M'Eachin*

(Signature)


*3/26/35*  
(Date)

*E. L. ...*  
(Title)

*J-9*

SECTION OF THE PUBLIC LANDS  
 SHOWING THE LOCATION OF THE CORNER  
 OF THE SECTION 16, T. 141 N., R. 29 E.,  
 MER.

Metal Location Poster is on a  
 tree 8" inches diameter, on the  
 side of *LOOK*  
 from which this Corner bears  
 100' *chains distant*  
 Give any further facts which will aid in finding this  
 Corner again  
*Corner in center of  
 road*



T. 141 N. R. 29 E. Mer. 5  
 (Make sketch of topography near Corner)  
 J. W.