

U. S. Department of Agriculture

FOREST SERVICE

M-10

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *29 W* *5th* Mer.

SW 1/16 Corner common to Sections *16*, _____, and _____



Corner consists of a *1" I.P.W/cap* (not) in place
State condition *good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

R. Moore

(Signature)

Asst. Dir. F.H.S.

(Title)

1/14/37
(Date)

M-10


8-11

Corner again.

Give any further facts which will aid in finding this
 obtain distant

from which this Corner bears N 55 E
 side of

tree 6 inches diameter, on the
 Metal Location Poster is on a Out



(Make sketch of topography near Corner)

M-10
Mor

5th

R. 29M

T. 14N