

U. S. Department of Agriculture
FOREST SERVICE

123
7-29-37
K-10
[Signature]

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 29W 5th Mer.

NW 1/6 Corner common to Sections
16, _____, and _____


Corner consists of a 1 1/2" M. w/ brass cap (not) in place
State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____
 Diameter _____
 Bearing _____
 Distance _____

Do you believe this to be a genuine Land Office Corner? [Signature]

If not, why? _____

July 27, 1936 (Date)
Carl Steadland (Signature)
Const. Fore (Title)
 K-10

Corner again.

Give any further facts which will aid in finding this


1.98 chains distant.

From which this Corner bears *S 80 E*

side of

tree 6 inches diameter, on the

Metal Location Poster is on a *post*

	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>

(Make sketch of topography near Corner)

K-10
Mer.

T 141 R 22