

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

123
7-29-37
P

Chippewa H-11
NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *14 N.* R. *29 W.* *5th* Mer.

OS 116 Corner common to Sections
9, _____, and _____


Corner consists of a *1/2" iron pin* (not) in place
State condition *Good*

Dimensions above ground *7* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steadland
(Signature)

July 30 1936
(Date)

Const. Fore
(Title)

H-11

Corner again.

Give any further facts which will aid in finding this

chains distant.

S 39 W

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

M. K. O. M.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

H-11

T. 141 R. 29

Mer.