

U. S. Department of Agriculture

FOREST SERVICE

R-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 29 W. 5th Mer. Section

Corner common to Sections 21, 22, 27, and 28

Corner consists of a 1" IM W/Brass Cap (not) in place


State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species R.Oak R.Oak

Diameter 14" 12"

Bearing N. 62° W. S. 14° W.

Distance 29 lks 31 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Arthur F. Johnson

(Signature)

Semi Skilled Worker

(Title)

2/15/38

(Date)

R-13

This corner lies ~~at~~ 2.50 chains west of old trail leading to Moccasin Lake.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

R-13

T. 141 N. R. 29 W. 5th Mer.