

U. S. Department of Agriculture
FOREST SERVICE

128
7-29-37
P

M-14

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 29 W. 5th Mer.


SW 1/16 Corner common to Sections
15, _____, and _____

Corner consists of a 1st I. N. with brass cap in place
State condition Good

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

July 1936
Date

Carl Steadland
(Signature)
Const. Fore
(Title)

M-14

14-11

Corner again.

Give any further facts which will aid in finding this

chain distant.

from which this corner bears

S 70 W

side of

tree 10 inches diameter, on the

Howeysville

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near corner)

14-11
Mer

T 141 R 29