

U. S. Department of Agriculture
FOREST SERVICE

102
229-37
[Signature]

Chippewa NATIONAL FOREST

N-15

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 29 W 5th Mer.

1/4 Corner common to Sections

15, and 22
Corner consists of a 1" I.M. Brass Cap (net) in place


State condition Good

Dimensions above ground 6" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Carl Steadland

(Signature)

July 1936

(Date)

Const. Fore

(Title)

N-15

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.62

from which this Corner bears

S72E

side of

tree 10 inches diameter, on the

Metal Location Poster is on a

Aspen

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

N-15 Mer.

T 141 R 29