

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

120
7-29-37
C.H.
P

N-18

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 29 W. 5th Mer.

W 1/16

Corner common to Sections

14, and 13

Corner consists of a "I. M. with handle" (not) in place



State condition Good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steadland

July 28, 1936
(Date)

Const. Serv.
(Title)

N-18

Corner again.

Give any further facts which will aid in finding this

chain distant: 0.11

from which this Corner bears

7836

side of

tree inches diameter, on the

Metal Location Poster is on a *Copier*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer. N-18

T 141 R 29