

U. S. Department of Agriculture  
FOREST SERVICE

*Rippewa*

*Posted*

*N-19*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141* R. *29* Mer. *5*

*1/4* Corner common to Sections  
*14*, and *23*

Corner consists of a *6.60 Brass Cap* (not) in place


State condition *Good*

Dimensions above ground *6"* inches

Sketch-grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_ *Oaks*

Diameter \_\_\_\_\_ *1 1/4"*

Bearing \_\_\_\_\_ *S. 25° W.*

Distance \_\_\_\_\_ *3.65*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*R. H. M'Pack*

(Signature)

*4/9/35*  
(Date)

*Estimator*


(Title)

*N-19*

Section 34  
Section 35  
Section 36  
Section 37

Corner again.  
B.T. 3 chains off field  
Fence on North side of  
field on line

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears N. 25° E.  
side of  
tree 14 inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 111  
R. 29  
Mer. N-19  
5