

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

123  
7-29-26  
P

*Chippewa* NATIONAL FOREST

M-19

CORNERS OF THE PUBLIC SURVEY

T. *14 N* R. *29 W* S. *5* Mer.

*@ 5 1/16*

Corner common to Sections

*14*

and

Corner consists of a *1/2" x 1/2" brass cap* (not) in place



State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Carl Steadland*  
(Signature)

*July 29 1926*  
(Date)

*Const. For.*  
(Title)

M-19

Corner again.

Give any further facts which will aid in finding this

0.05 chains distant.

from which this Corner bears

0.31 E

side of

tree 6 inches diameter, on the

Metal Location Poster is on a

Copy

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

M-19

Mer.

T. 141 R. 29