

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

120  
7-27-37  
*[Signature]*

020

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *29 W* *5<sup>th</sup>* Mer.

*NE 1/4* Corner common to Sections  
*23*, \_\_\_\_\_, \_\_\_\_\_, and \_\_\_\_\_



Corner consists of a *1" I.M. with brass cap* (not) in place  
State condition *Good*

Dimensions above ground *15"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

*July 27, 1936*  
(Date)

*Carl Steadland*  
(Signature)  
*Const. Foreman*  
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree 5 inches diameter, on the

*at corner*  
Metal Location Poster is on a *corner post*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

0-20

Mer.

R. 29

T. 141