

U. S. Department of Agriculture

FOREST SERVICE

R-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 29 W. 5th Mer.

Section Corner common to Sections

23, 24, 25, and 26

Corner consists of a Iron Pipe & Brass Cap (not in place)

State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

		T. 141	R. 29	W.		
		S. 23	244			
		28	25			

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 141 N.			
R. 29 W.			
S. 25			

Species W. Oak

Diameter 12"

Bearing S: 16° E

Distance 1.09 Ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Peter J. Johnson

(Signature)

Semi Skilled Worker

(Title)

1/21/38

(Date)

R-21

Corner sets at South edge of
 grass swale about 20 chains South of
 old Longville R.R. grade.

Corner again.

Give any further facts which will aid in finding this


1.09 chains distant.

from which this Corner bears
 N. 16° W.

side of Tree

tree 12 inches diameter, on the Northwest

Metal Location Poster is on a White Oak



(Make sketch of topography near Corner)

T. 141 N. R. 29 W. 5th Mer. 8-21