

U. S. Department of Agriculture
FOREST SERVICE

Cippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 29W 5 Mer.

1/4 Corner common to Sections 22, and 24

Corner consists of a Br. Capl pipe (~~rod~~) in place
State condition good

Dimensions above ground 2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>S29</u>

<u>1/4</u> <u>S23</u>

--

--

<u>BT</u>

<u>BT</u>

--

--

Species Aspen 1500

Diameter 10" 10"

Bearing N48°E S10°W

Distance 2616 358

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Daniel Rose

(Signature)

April 5, 35
(Date)

Estimator
(Title)

1918
523/524
1/4

Corner again.

Give any further facts which will aid in finding this

chains distant.

216.6

from which this Corner bears


572.11

side of

tree inches diameter, on the

Normal
911

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

5th

R. 2900

T. 191N

P-21

10/2

U. S. Department of Agriculture

FOREST SERVICE

CU
P-21
282

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 29 W. 5th Mer.

1/4

Corner common to Sections

23, and 24.

Corner consists of a 1" I.M. W/ Brass ~~(Box)~~ in place

State condition Good

Dimensions above ground 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			1/4	23/24			
--	--	--	-----	-------	--	--	--

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 141 N.	T. 141 N.		
R. 29 W.	R. 29 W.		
Sec. 23	Sec. 24		
B. T.	B. T.		

Species R. Pine J. Pine _____

Diameter 10" 12" _____

Bearing N. 55° E S. 18° W. _____

Distance 2.61 Ch. 3.59 Ch. _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Arthur J. Johnson
(Signature)

1/24/38

(Date)

Semi Skilled Worker

(Title)

P-21

Corner again.

Give any further facts which will aid in finding this

chains distant.


2.61

from which this Corner bears S. 55° W.

side of Tree

tree 10 inches diameter, on the Southwest

Metal Location Poster is on a R. Pine



(Make sketch of topography near Corner)

T. 141 N. R. 29 W. 4th Mer. 2/22