

U. S. Department of Agriculture  
FOREST SERVICE

*Card 2*  
*R-23*

*Chippewa* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. *191 N* R. *29 W* Mer.

*1/4* Corner common to Sections  
*21*, and *25*


Corner consists of a *Brass 1" pipe* (~~rod~~) in place  
State condition *good*

Dimensions above ground *8"* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *W. Oak* \_\_\_\_\_

Diameter *12"* \_\_\_\_\_

Bearing *N15° W* \_\_\_\_\_

Distance *126.1* \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

\_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

*April 9/35*  
(Date)

*Harold [Signature]*  
(Signature)  
*[Signature]*  
(Title)



Corner again.


Give any further facts which will aid in finding this

from which this Corner bears chains distant.

side of

tree 4" inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

1173  
8-23  
Mer.

T. 191N R. 29W

U. S. Department of Agriculture

FOREST SERVICE

Post  
R-23  
27

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 29 W. 5th Mer.

1/4

Corner common to Sections

24, and 25

Corner consists of 1" I.M. W/ Brass ~~Cap~~ in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			1/4 24 25				
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Arthur J. Johnson

(Signature)

Semi Skilled Worker

(Title)

1/24/38

(Date)

R-23

Lake.

5.59 Chains East of Silver

Corner again.

Give any further facts which will aid in finding this


6.52 chains distant.

from which this Corner bears N. 68° E.

side of Tree

tree 6" inches diameter, on the Northeast

Metal Location Poster is on a Oak



(Make sketch of topography near Corner)

R-23

T. 141 N. R. 29 W. 5th Mer.