

U. S. Department of Agriculture

FOREST SERVICE

172  
7-219-37  
*[Handwritten initials]*

L-23

*Chippewa*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 29 W. 5<sup>th</sup> Mer.

*C 1/4*

Corner common to Sections

*13*

and

Corner consists of a *1" I.M. with brass cap* (not) in place



State condition *Good*

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Carl Steadland*

(Signature)

*Const. Fore*

(Title)

*July 1936*  
(Date)

L-23

(Make sketch of topography near corner)

Mer. 4-23

T. 141 R. 29

	Sec.		Sec.
	Sec.		Sec.

Metal Location Poster is on a *Red Oak*

tree 6 inches diameter, on the

side of

from which this corner bears

*N 41 W*

*0 7 2*  
chains distant.

Give any further facts which will aid in finding this

Corner again.