

U. S. Department of Agriculture

FOREST SERVICE

N-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 28-29 W 5th Mer.

Section Corner common to Sections

13, and 24

Corner consists of a 2" I.M. & brass cap in place

State condition Fair

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Y&S

If not, why?

Arthur P. Johnson

Arthur P. Johnson

(Signature)

Semi-skilled Worker

(Title)

3/29/38

(Date)

N-25

This corner lies just on the east side of Town line road between T. 141-28 & T. 141-29.

Corner again.

Give any further facts which will aid in finding this


0.30 chains distant.

from which this Corner bears West

side of road

tree inches diameter, on the east

Metal Location Poster is on a fence post



(Make sketch of topography near Corner)

T. 141 N R. 29 W 5th Mer. N-25