

U. S. Department of Agriculture
FOREST SERVICE

123
7-29-36
K-1213

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 29 W 5th Mer.

S. M. C.

Corner common to Sections

16 - located 6.75 chs. E. of NE 1/4 corner and

Corner consists of a 1" I.P. w/ brass cap (not) in place



State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

(Signature)

July 29, 1936

(Date)

Const. Sec.

(Title)

K-12-13

Corner again.

Give any further facts which will aid in finding this

from which this Corner bears 1.30 chains distant.

N 40 E

side of

tree inches diameter, on the

M.T.O.R.
Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

R-1213
Mer.

T. 141 R. 29