

U. S. Department of Agriculture

FOREST SERVICE

123
#2927
M-18-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N.* R. *29 N.* *5th* Mer.

S. M. C. Corner common to Sections
14 located *12.61 chs. N. of CS 16 S. 14*
and _____

Corner consists of a *1" Z.M. w/ iron cap* (not) in place



State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steadland

(Signature)

Const. Sec.

(Title)

July 29, 1936

(Date)

M-18-19

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

at corner

4 inches diameter, on the

Metal Location Poster is on a

Copied from

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mar

T. 141 R. 29