

U. S. Department of Agriculture

FOREST SERVICE

173
7-29-37
[Signature]

Chippewa NATIONAL FOREST

MN-18

CORNERS OF THE PUBLIC SURVEY

T. *141 N.* R. *29 W.* *5th* Mer.

S. M. C.

Corner common to Sections

14 - located 5.78 ch. N. of 7 1/16 *314*
and *523*

Corner consists of a *1" T.M. w/ brass cap* (not) in place



State condition *good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steadman

(Signature)

July 28, 1936

(Date)

Cons. For.

(Title)

MN-18

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears *N 3 E*

side of

tree *6* inches diameter, on the

Metal Location Poster is on a *Dennard*



(Make sketch of topography near Corner)

M N - 18
Mer

T. 141 R. 29