

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 29 W 5th Mer.

1/64 Corner common to Sections
23, and



Corner consists of a 1 1/2" Brass Cap (not) in place
State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Corner is located 10 chains
North of C 1/4 S 23

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why?

Carl Steadland

(Signature)

July 24, 1936

(Date)

Const. For

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.52

from which this Corner bears

S54 E

side of

tree 8 inches diameter, on the

Metal Location Poster is on a

Aspen

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

OP-19

Mer.

T 141 N R 29 W 5th