

U. S. Department of Agriculture

FOREST SERVICE

RS-16 posted 12/11/40

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 29 W 5 Mer.

CC E 1/16 Corner common to Sections 27, and _____

Corner consists of a 1" pipe & brass ^{cap} ~~(rod)~~ in place



State condition Good

Dimensions above ground 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species R P

Diameter 12"

Bearing N29°W

Distance 25 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Henry D. Zimmerman
(Signature)

Jr. Forester, P-1

10-14-40
(Date)

(Title) R-5-16-17


Corner again. This corner is the E 1/16 closing corner on the old Indian Reservation line in this section.

Give any further facts which will aid in finding this chains distant.

From which this Corner bears S 29° E side of

tree 10 inches diameter, on the

Metal Location Poster is on a B.T. Red Pine



(Make sketch of topography near Corner)

R 5-16

T. 141 N. R. 29 W. S. Mer.