

U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 31 5 Mer.

146 Corner common to Sections 6 and 7



Corner consists of a IRON PIPE (not) in place State condition GOOD

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N

W

S

E

NW

SW

SE

NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? COUNTY SUBDIVIDED


4/1/35- (Date) Dan Pruitidge (Signature) Estimator (Title)

Corner again.

Give any further facts which will aid in finding this

~~382 LINKS distant~~

from which this Corner bears N 12° E  
side of CORNER  
tree 3 inches diameter, on the SOUTH  
Metal Location Poster is on a ~~MAP~~ SPEN



(Make sketch of topography near Corner)

T. 141 R. 31 Mer. 5