

Form 874-8—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Dusted

Chippewa NATIONAL FOREST *E22*

CORNERS OF THE PUBLIC SURVEY

T. 41 N. R. *31 W.* *5th* Mer.
Tract



Corner common to Sections
1, and *12*

Corner consists of a *Brcep. iron* (~~rod~~) in place
State condition *9009*

Dimensions above ground *1 x 18"* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *None*

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Dorman Sutton

(Signature)

Engineer

(Title)

3-12-34

(Date)

Corner again.
Give any further facts which will aid in finding this

chains distant.

from which this Corner bears


SE

side of

tree 26 inches diameter, on the

SE
EIM

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

5th

R 31

T 141 N