

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

*Posted* A14

CORNERS OF THE PUBLIC SURVEY

T. *141+142* R. *31 W.* *5th* Mer.

*16* Sixteenth Corner common to Sections

\_\_\_\_\_, \_\_\_\_\_, *34*, and *3*

Corner consists of a *Cap. iron pipe* in place



State condition *good*

Dimensions above ground *2 x 20* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *None*

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *Established by County surveyor.*

*Dorman J. Sutton*

(Signature)

*Engineer*

(Title)

*9/11/35*  
(Date)

Corner again.

Give any further facts which will aid in finding this

old chains distant.

from which this Corner bears


West

side of tree

tree 11 inches diameter, on the

East N. Pine

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

575

T. 114 N. R. 31 N.