

U. S. Department of Agriculture
FOREST SERVICE

123
329 37
16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 31 W 5th Mer.

1/4 Corner common to Sections
15, and 22

Corner consists of a 4" Aspen post (not) in place
State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? _____

Approximate location

Established by C.C.C. crew

Carl Steadfast

(Signature)

Const. For

(Title)

Dec. 23, 1936
(Date)

Corner again.

Give any further facts which will aid in finding this


0.12 chains distant.

from which this Corner bears 5.39W

side of

tree 8 inches diameter, on the

Metal Location Poster is on a *Yock line*



(Make sketch of topography near Corner)


N-15

Mer.

Sta

T. 141 N. R. 31 W.

Metal Location Poster is on a *back line*
 tree *8* inches diameter, on the
 side of
 from which this Corner bears *539 W*
0.12 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. H. I. N. R. 31 W. S. 7th Mer.