

**U. S. Department of Agriculture**  
**FOREST SERVICE**

N17

*Chippewa* NATIONAL FOREST  
**CORNERS OF THE PUBLIC SURVEY**

T. *14 N.* R. *31 W.* *5th* Mer.

Corner common to Sections

*14, 15, 22, and 23*Corner consists of a *2" Gal. I.P.* (not) in placeState condition *Good*Dimensions above ground *15"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *No.*

If not, why? \_\_\_\_\_

*This is a county corner*


*Carl Steadland*  
(Signature)

*Dec. 8, 1936*  
(Date)

*Coast Twp.*  
(Title)

Metal Location Poster is on a *Aspen* tree *10* inches diameter, on the side of *N 47 W* from which this Corner bears *0.52* chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 141 N. R. 31 W. 5th Mer.