

U. S. Department of Agriculture  
FOREST SERVICE

119

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 31W 5th Mer.

C.S. 46 Corner common to Sections  
-----, -----, -----, and 26

Corner consists of an IRON PIPE (not) in place  
State condition GOOD

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? NO

If not, why? APPARENTLY SET BY  
COUNTY ENGINEER

Arthur J. Johnson

(Signature)

Levi Fred Walker

(Title)

12/14/27

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 N. R. 31 W. 5th Mer.