

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

*Noted* P19

CORNERS OF THE PUBLIC SURVEY

T. 14 N. R. 31 W. 5<sup>22</sup> Mer.

Quarter Corner common to Sections

23, and

Corner consists of a *Not found* (not) in place


State condition

Dimensions above ground \_\_\_\_\_ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *N. Pine*

Diameter *18"*

Bearing *South*

Distance *30*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*Dorman Sutton* (Signature)

*Mar. 7, 1935* Engineer (Title)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.


30

from which this Corner bears North

side of trees

tree 18 inches diameter, on the N

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T. 111 R. 31 Mer. 5th