

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

A-2324

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 31 W. 5th Mer.

Witness Marker Corner common to Sections
Sec. 1-141-31, and 36-142-31

Corner consists of a 1" Iron & Brass Cap in place
State condition Good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			WC	S. 36 S. 1				
			MC					
N	W	S	E		NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Arthur T. Johnson
Arthur T. Johnson
(Signature)

2/9/38
(Date)

Semi Skilled Worker
(Title)

This corner is 28.35 chains
 West of corner in road just north of
 Camp 7-48. Trail from camp to Lanch
 Lake is 30 lks. North of this corner.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

A-23-24