

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

ST-13

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 31 W. 5th Mer.

Meander Corner common to Sections

28, and 27

Corner consists of ~~a~~ bearing trees (not) in place

State condition stake not to be found

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T141 R31 S27	Grown over		
MC			

Species W. Oak W. Pine

Diameter 10" 18"

Bearing N89E N89E

Distance 18 18

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Dorman J. Sutton

(Signature)

Engineer

(Title)

3/21/35
(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


.18

from which this Corner bears $S 39^{\circ} E$

side of tree

tree 18 inches diameter, on the S E

Metal Location Poster is on a W.P. line



(Make sketch of topography near Corner)

Mer.

5th

R. 31W

T. 141N