

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

216-17

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 31W 5th Mer.

Meander Corner common to Sections
3~~4~~, East of C¹/₄, and

Corner consists of an iron pipe (not) in place
State condition good

Dimensions above ground 2x24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

None

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Weathered			

Species N. Pine

Diameter 16

Bearing West

Distance 70

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Dorman J. Sutton

(Signature)

Engineer

(Title)

3/21/35
(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

None

<p>Sec. 34</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>

(Make sketch of topography near Corner)

T. 141N R. 8/W S 1/4 Mer.