

U. S. Department of Agriculture

FOREST SERVICE

N-15

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 24 S. Mer.

1 Corner common to Sections

18, and 20

Corner consists of a ~~not found~~ ~~log~~ in place


State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B.T.



Species W.P.

Diameter 147

Bearing N 80° E

Distance 22 1/2

Do you believe this to be a genuine Land Office Corner?

If not, why? COUNTY CORNER

R. T. Deford
Raymond T. Deford

(Signature)

Jr. Clerk

10/27/08

(Date)

Corner again.

Give any further facts which will aid in finding this chain distant.

from which this corner bears

side of tree

tree 1.6 inches diameter, on the

Metal Location Poster is on a

