

U. S. Department of Agriculture

FOREST SERVICE

J-19

CHIPPWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 26 W 5th P. Mer.

Corner common to Sections 11, and 14

Corner consists of a Cedar post & iron (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

11		14	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/8			
B.T.			

Species Spr. Pine

Diameter 2 1/2

Bearing N 55 30 E

Distance 0.08

Do you believe this to be a genuine Land Office Corner?

If not, why? TO

Arthur H. Jager

7/12/26

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

Due north

side of


Post

inches diameter, on the

South

Metal Location Poster is on a

James Post



(Make sketch of topography near Corner)