

U. S. Department of Agriculture

FOREST SERVICE

VII

~~CHIPPENAW~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 27 5 Mer.

$\frac{1}{2}$ Corner common to Sections
~~123~~, and ~~133~~



Corner consists of a Not Found (not) in place
 State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J.P.

Diameter 14"

Bearing N.

Distance .74

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? B.T. tree down.

R. T. Defant
 Raymond T. Defant

(Signature)

Jr. Civil Engineer

(Title)

6-17-40

(Date)

W

C. L. ...

2 57 145

Locations in B.L. ...

... of ...

Corner again.

Give any further facts which will aid in finding this

... change distant.

18

from which this ... bears

S60° E


The ...

tree 8 inches diameter, on the

N W

Metal Location Poster is on a

W ...



9-15-40 (Make sketch of topography near ...)