

U. S. Department of Agriculture
FOREST SERVICE

X13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 27 S. 5 Mer.

1

Corner common to Sections

33

and 34

Corner consists of a 6 1/2 pipe & post (not) in place

State condition Good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/2</u> S		<u>1/4</u> S
	<u>33</u>		<u>34</u>
N	W	S	E

			<u>27</u>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/2 cor
Sec 34

1/4 cor
Sec _____

33 NE

14 NE

Species cedar tan.

Diameter 12 in. 24 in.

Bearing N55E N20E

Distance 33 lks. 14 lks.

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

R. T. DeFaut

R. T. DeFaut

(Signature)

2-22-41

(Date)

J. R.

(Title)

Corner again. Just at the edge of cedar swamp

Give any further facts which will aid in finding this


15. ... chains distant

from which this Corner bears **SM**

side of tree

tree 5 inches diameter, on the **NE**

Metal Location Poster is on a **Pa 150m**



(Make sketch of topography near Corner)