

U. S. Department of Agriculture

FOREST SERVICE

Posted
12/11/40
L23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 27 5 Mer.

0 1/2

Corner common to Sections

13, and

Corner consists of a Post (30) in place

State condition good

Dimensions above ground 10' 1" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Corner

R. T. DeFant
Raymond T. DeFant
(Signature)

Jr. Civil Engineer

(Title)

10/17/40

(Date)

UNITED STATES DEPARTMENT OF AGRICULTURE
BUREAU OF PLANT INDUSTRY

PLANT INDUSTRY

PLANT INDUSTRY

PLANT INDUSTRY

PLANT INDUSTRY

PLANT INDUSTRY

PLANT INDUSTRY

Corner again

Give any further facts which will aid in finding the


contains distant

from which this Corner bears

side of

tree 2 1/2 inches diameter, on the S.W.

Metal Location Posters on a



(Please sketch of topography and general appearance)

Mer.

5

R.

T. 100