

U. S. Department of Agriculture

FOREST SERVICE

Posted V-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 28W 5th Mer.

Section Corner common to Sections
31, 32, 30, and 29

Corner consists of a B.C. 2" pipe (not) in place
State condition good

Dimensions above ground 14" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>T142N</u> <u>R28W</u> <u>332</u> <u>B.T.</u>	<u>T142N</u> <u>R28W</u> <u>332</u> <u>B.T.</u>	<u>T142N</u> <u>R28W</u> <u>329</u> <u>B.T.</u>	<u>T142N</u> <u>R28W</u> <u>930</u> <u>B.T.</u>	<u>cutoff</u>
--	--	--	--	---------------

<u>B.T.</u>	<u>B.T.</u>	<u>B.T.</u>	<u>B.T.</u>	<u>B.T.</u>
-------------	-------------	-------------	-------------	-------------

Species <u>Cedar</u>	<u>Cedar</u>	<u>Tam.</u>	<u>Birch</u>	<u>Cedar</u>
Diameter <u>12"</u>	<u>12"</u>	<u>12"</u>	<u>12"</u>	<u>10"</u>
Bearing <u>S47°E</u>	<u>S22°E</u>	<u>N43°E</u>	<u>S89°W</u>	<u>S43°W</u>
Distance <u>23.6ks</u>	<u>29.6ks</u>	<u>26.4ks</u>	<u>27.6ks</u>	<u>75.7</u>

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Daniel Rose
Estimator

Mar. 25 1935
(Date)

(Title)

Section 31

Section 32

Right in cedar swamp 1 1/2 mile
3 posts black and 5/8" and 1/2"
5 1/2" scribbled post

Corner again.

Give any further facts which will aid in finding this

chain distant


5280 E

from which this Corner bears

side of Tr. 2

10 inches diameter, on the S E

Metal Location Poster is on a Cedar Stump



(Add sketch of topography near Corner)

T. 122 N. R. 28 W.

57th Mer.

V-5