

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 28W 5 Mer.

C/4 Corner common to Sections
32, _____, _____, and _____



Corner consists of a 1" I.P. w/ brass Cap (not) in place
State condition good

Dimensions above ground 6" _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Many are skaled over</u>			

Species W. Oak _____

Diameter 13" _____

Bearing N 36 1/2° W. _____

Distance 0.96 chs. _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. Carl E. Steadland

(Signature)

Foreman

(Title)

5/22/39

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.96


From which this Corner bears

S 36 1/2 E

side of

tree 13 inches diameter, on the

Metal Location Poster is on a W. Oak



(Make sketch of topography near Corner)

T. 142N R. 28W S Mer. X-7