

U. S. Department of Agriculture
FOREST SERVICE

Chippewa

NATIONAL FOREST

Posted 6-7

CORNERS OF THE PUBLIC SURVEY

T. *142* R. *28* S. *5* Mer.

Cor 1/4 Corner common to Sections *8*, and _____

Corner consists of a *Wood post (set)* in place
State condition *Good*

Dimensions above ground *4" x 4" x 4"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

<i>Sec 8</i>			
<i>Cor. 1/4 Cor.</i>			

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<i>No AC</i>		

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*


If not, why? _____

3/20/35
(Date)

R. G. W. Cooper
(Signature)
Estimator
(Title)

Corner again.
located at 1/4 Sec. North
of Lake shore in Non-
productive Swamp

Give any further facts which will aid in finding this
chain's distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal location poster is on a
None place & Swamp



(Make sketch of topography near Corner)