

U. S. Department of Agriculture
FOREST SERVICE

X-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 28 W 5 Mer.

1/4 Corner common to Sections
32, 33



Corner consists of a 1" I.P. w/ brass cap (net) in place
State condition good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter None

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl E Steadland

(Signature)

Foreman

(Title)

5/22/39

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant. *0.25*

from which this Corner bears *West*

side of

tree inches diameter, on the

Metal Location Poster is on a *FRAGR POST*



(Make sketch of topography near Corner)

T. 142N R. 28W
5
Mer. X-9