

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

Plotted V-9

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 28 S. 5 Mer.

Section 32, 33, 28, and 29 Corner common to Sections



Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____ Tamarack
Diameter _____ 8 inch
Bearing _____ N45°E (?)
Distance _____ ?

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

B Hutchinson

(Signature)

Estimator

(Title)

3/25/35
(Date)

Corner again.
There is a trail running
E. & W. thru the probable location
of the corner.
The markings on the B.T.
are very vague & barely
discernible.

Give any further facts which will aid in finding this
chain distant.
from which this Corner bears
side of Telephone Pole
tree 6 inches diameter, on the South
Metal Location Poster is on a Telephone Pole

<p>33</p> <p>Sec.</p>	<p>32</p> <p>Sec.</p>		
<p>28</p> <p>Sec.</p>	<p>29</p> <p>Sec.</p>		

(Make sketch of topography near Corner)