

U. S. Department of Agriculture
FOREST SERVICE

R-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 28 5 Mer.
Quarter Corner common to Sections

21, and 28

Corner consists of a G.L.O. Cap (not) in place

State condition Good

Dimensions above ground 14 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
21		28	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$	
S 21	

$\frac{1}{4}$	
S 28	

B.T.	
------	--

--	--

B.T.	
------	--

--	--

Species Cedar _____ Cedar _____

Diameter 6 inch _____ 6 inch _____

Bearing North _____ South _____

Distance 18 links _____ 20 links _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

D. Hutchinson

(Signature)

3/27/35

(Date)

Estimator

(Title)

Section 28

Section 21

Section 28

Section 21

Found in Cedar Swamp.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Pester is on a



(Make sketch of topography near Corner)

MR-11

5

R. 28

T. 142