

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

*Posted X-13*

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 28 W 5 Mer.

Corner common to Sections 33, and 34

Corner consists of a G.L.O. Cap in place State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	33		34
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	M.C. L A 533		
	B.T.		

Species *Aspen*  
 Diameter *10 inch*  
 Bearing *N 80° W*  
 Distance *3 chns, 68 links*

Do you believe this to be a genuine Land Office Corner? *yes*  
If not, why?

*L. B. Hutchinson*

*Estimator*  
(Signature) (Title)

*4/2/35*  
(Date)

This telephone line runs on the quarter line & passes right by the corner.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of *Pole*

tree 6 inches diameter, on the *East*

Metal Location Poster is on a *Telephone Pole*



(Make sketch of topography near Corner)

T. 142 N. R. 28 W. 5 Mer. X-13