

U. S. Department of Agriculture  
FOREST SERVICE

*Filed 6-13*

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 142 R. 28 5 Mer.  
Quarter Corner common to Sections

9, and 10

Corner consists of a G.L.O. Cap (~~not~~) in place  
State condition Good

Dimensions above ground 10 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_ Oak  
Diameter \_\_\_\_\_ 10 inch  
Bearing \_\_\_\_\_ N 75° E  
Distance \_\_\_\_\_ 70 links

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? \_\_\_\_\_

*B. Hutchinson*


(Signature)

Mar. 21  
(Date)

*Estimate*  
(Title)

Corner again.  
 This poster is on a fence  
 post right above the G.L.O. cap.  
 The corner is at the  
 intersection of two fences; one  
 running N. 85, the other E. 8 W.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree 8 inches diameter, on the  
 Metal Location Poster is on a Fence Post



(Make sketch of topography near Corner)

T. 142 R. 28  
 G-13 Mer. 5