

U. S. Department of Agriculture

FOREST SERVICE

*Plotted T-27*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142N* R. *28W* Mer.

*1/4* Corner common to Sections

*26*, and *27*

Corner consists of a *Break 1" pipe (not)* in place



State condition *good*

Dimensions above ground *8"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Tw. Bull Oak Bull Oak*

Diameter *18" 14"*

Bearing *S89°W S60°E*

Distance *70.285 31.245*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Daniel Rose Jr.*

*April 1, 1935*  
(Date)

(Signature)  
*Estimator*  
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant,

from which this Corner bears

side of

tree  $\frac{1}{2}$  inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 192N R. 28W S Mer. 5-17