

U. S. Department of Agriculture
FOREST SERVICE

Walker
Chippewa NATIONAL FOREST

Posted N-17 142

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 28 W 5 Mer.
Section Corner common to Sections

14, 15, 22, and 23

Corner consists of a G.L.O. Brass Cap (net) in place
State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

					15	22	23
							14
N	W	S	E	NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			T-1 B-28 S-74
			B.T.

Species Dead Tomarock

Diameter 2 1/2 in.

Bearing N55° E

Distance 9 1/2 miles


Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

March 19, 1936 Estimator
(Date) (Title)

Corner again.
 Give any further facts which will aid in finding this
 from which this Corner bears
 side of

tree 5 inches diameter, on the East
 Metal Location Poster is on a Dead Tomrack
 9 miles distant.
 555° W



(Make sketch of topography near Corner)

T. 142 R. 28
 Mer. 5
 N-17
 182

U. S. Department of Agriculture

FOREST SERVICE

N-17

Chippewa already posted
NATIONAL FOREST 297

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 28W 5th Mer.

Section Corner common to Sections

14, 15, 22, and 23

Corner consists of a Cedar Stake (not) in place

State condition Fair

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

T142N R28W S14	T142N R28W S15	T142N R28W S22	T142N R28W S23
----------------------	----------------------	----------------------	----------------------

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T142N R28W S15

T142N R28W S22

T142 S14

--

--

--

--

--

Species Cedar Tam. Tam.

Diameter 8" 6" 6"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Gordon R. Heath

(Signature)

Jr. Forester

(Title)

6/18/37
(Date)

Original Section line
still visible
Resurveyed Corner
beside original

Corner again.

Give any further facts which will aid in finding this
chains distant.

from which this Corner bears
side of

tree inches diameter, on the

Metal Location Poster is on a
Original Post

	Sec.		Sec.
	Swamp	Cedar	
		+	
	Sec.	Flat	Sec.
		Tamarack	

(Make sketch of topography near Corner)

T. 142N R. 28W
Merrill
N-17