

U. S. Department of Agriculture
FOREST SERVICE

Posted
X-22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 28 W 5th Mer.

116 Corner common to Sections
36

Corner consists of a Brass pipe (not) in place
State condition good

Dimensions above ground 1 1/2 x 1 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>Q.W. 1/2</i> <i>536</i>			
<i>B.T.</i>			

Species *Dead* B. Spruce

Diameter 3

Bearing N 12° E

Distance 9 Lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

David Rose
(Signature)

Mar 13, 35
(Date)

Estimator
(Title)



Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *Nova Lead*



(Make sketch of topography near Corner)

T. 192N R. 27E28W 5th Mer.