

U. S. Department of Agriculture
FOREST SERVICE

A-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14² R. 2⁹ Mer.

E 1/16 Corner common to Sections
36, and 1

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species P. Stp _____

Diameter 2 1/2" _____

Bearing N 68 E _____

Distance 70 L. _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

G. Sherman

(Signature)

3/6/35

(Date)

Engineer

(Title)

Handwritten notes on ruled lines, including the word "POST" written vertically in several places.

Corner again.

Give any further facts which will aid in finding this

chains distant.

SA 5 =


from which this Corner bears

side of

7 inches diameter, on the N.E. Post

Metal Location Poster is on a

TEI Post



(Make sketch of topography near Corner)

A-24 Mer.

T. 142 R 28