

U. S. Department of Agriculture
FOREST SERVICE

4-6,7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 28 W. 5 Mer.

164 Corner common to Sections
32, _____, _____, and _____


Corner consists of a 1" IP, w/ brass cap (not) in place
State condition good

Dimensions above ground 1" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species None _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

C. E. Steadland

(Signature)

Foreman

(Title)

5/23/39

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

None



(Make sketch of topography near Corner)

Mer.

R. 28 W.

T. 14 N.

5

Y-6,7